


1. PLASMATECH-NOVA

1.1 - Machine DIMENSIONS



Useful cutting		Dimensions				Weight TOT.
X Width	Y Length	W Width	L Length	H Height	Wmax	Weight
1500 (5 ft)	3000 (10 ft)	2180 7.2 ft	4625 (15.3 ft)	2400 8 ft	2800 9.3 ft	2848 kg.
	4000 (13 ft)		5750 (19 ft)			3530 kg.
	6000 (20 ft)		8000 (26.4 ft)			4895 kg.
	8000 (26,5 ft)		9690 (32 ft)			6260 kg.
2000 (6.5 ft)	4000 (13 ft)	2680 8.9 ft	5750 (19 ft)	2400 8 ft	3300 11 ft	4590 kg.
	6000 (20 ft)		8000 (26.4 ft)			6410 kg.
	8000 (26,5 ft)		9690 (32 ft)			8230 kg.
	10000 (33 ft)		11940 (39.5 ft)			10050 kg.
	12000 (39.5 ft)		13625 (45 ft)			11870 kg.
2500 (8 ft)	6000 (20 ft)	3180 10.5 ft	8000 (26.4 ft)	2400 8 ft	3800 12.6 ft	7925 kg.
	8000 (26,5 ft)		9690 (32 ft)			10200 kg.
	10000 (33 ft)		11940 (39.5 ft)			12475 kg.
	12000 (39.5 ft)		13625 (45 ft)			14750 kg.
	14000 (46 ft)		16450 (54.3 ft)			17025 kg.
3000 (10 ft)	6000 (20 ft)	3680 12.2 ft	8000 (26.4 ft)	2400 8 ft	4300 14.2 ft	9440 kg.
	8000 (26,5 ft)		9690 (32 ft)			12170 kg.
	10000 (33 ft)		11940 (39.5 ft)			14900 kg.
	12000 (39.5 ft)		13625 (45 ft)			17630 kg.
	14000 (46 ft)		16450 (54.3 ft)			20360 kg.

1.2 - PERFORMANCE

maximum speed axis X-Y	60 m/min 198 ft/min.	
Maximum speed axis Z	8 m/min 26 ft/min.	